

# Checklist after power failure

1. Check IGP Controller for R1 + R2, Current should be below 2 mA
2. Check Meerstetter TEC for R1 + R2 + ECDL (ResLab PC)
3. Check the H-Maser (ResLab Maser)

From:

<https://iqwiki.iqo.uni-hannover.de/> - IQwiki

Permanent link:

<https://iqwiki.iqo.uni-hannover.de/doku.php?id=groups:mg:failurechecklist&rev=1475783599>

Last update: **2016/10/06 19:53**

