


We install a door from the acoustic box and saw a heating process. At 16:27 we relieve the door. It can be seen that the temperature from R2 rises faster than R1. The reason for this is that R2 hasn't a complete acoustic/heating shield.



From:
<https://iqwiki.iqo.uni-hannover.de/> - IQwiki

Permanent link:
<https://iqwiki.iqo.uni-hannover.de/doku.php?id=groups:mg:reslab:labbook:2017-01:labbookentry-2017-01-02>

Last update: 2017/01/06 11:40

