02.11.2016

- 8x sinkings for the vitonballs in each panel:



- We measured the diameter of the glasballs and saw an inaccuracy of **80mm +/- 20müm**. Therefore we put the balls in a 5mm test-hole and measured the ball-high in different position with the CNC-maschine:



- After the “ball-high-measurement”, we calculated the mean value and drilled again test-holes, for example “Kugel 1” **5mm + 19.4müm**, and measured again. We saw a really nice result! After a 1cm test-milling and a good result, we milled in the mounting-breadboard:











- We build everthing together and measured the high of the mounting on different places with a provisional result of **+/- ~80müm**:



From:
https://iqwiki.iqo.uni-hannover.de/ - **IQwiki**

Permanent link:
https://iqwiki.iqo.uni-hannover.de/doku.php?id=groups:mg:project_ptb-cavity:labbook:2016-11:labbookentry-2016-11-02&rev=1478617172

Last update: **2016/11/08 14:59**