


Highfinesse Wavemeter WS/6-200



Calibration with the Wutz-light is necessary at least once a year! Otherwise the wavemeter doesn't show the right frequency, because it has a drift!



From:

<https://iqwiki.iqo.uni-hannover.de/> - IQwiki

Permanent link:

https://iqwiki.iqo.uni-hannover.de/doku.php?id=groups:mg:highfinesse_wavemeter&rev=1481720917

Last update: 2016/12/14 13:08

