#### **Jour Fixe**

SS, WFP

### Atomslab

• Laser 2 TA lenses were repositioned, because they had misaligned during AC shut down

### Reslab

- Frequency-Comb does not mode-lock
- AC and DC values do not suggest that LD is broken
- Clock TA is coupled: 180 mW @ 1,2 A

# Quench

• SHG-Board has moved to Atoms Lab on the clock laser table

## **PTB/Meta-mirror**

• Referencemirrors were characterized, next will be the Meta-mirrors

