



Highfinesse Wavemeter WS/6-200



Calibration with the Wutz-light is necessary at least once a year! Otherwise the wavemeter doesn't show the right frequency, because it has a drift!



Don't forget to push the "Start" button



From:
<https://iqwiki.iqo.uni-hannover.de/> - IQwiki

Permanent link:
https://iqwiki.iqo.uni-hannover.de/doku.php?id=groups:mg:private:resonatoren:reslabcomputers:highfinesse_wavemeter_ws_6-200&rev=1578992086

Last update: 2020/01/14 08:54

