


Temperature and vacuum pressure monitoring

- Setup:

rasptemp2.pdf



Temperature

We use the temperature monitoring design, made by E. Wodey, for the out of loop measurements during the out baking.

- Talk by E. Wodey for the explanation of the monitoring system:
2016-08_geoq_ctp_ew.pdf
- Temperature sensors: <http://www.omega.de/pptst/5SRTC.html>
 - Datasheet:
Chromega 5SRTC-TT-E-24-80
- Box-design:

