


19.10.2016


- I cleaned the vacuum chamber



- I tested the M6 holes from vacuumchamber



all threads are deep enough!




- 2x M4-breadboards (Incouple and otcouple) and there spacers are done!
- I assembled the mounting with vitonballs and zerodur rods.



We need two vitonballs of each metal sheet side. Otherwise the mounting is to wobbly!



8x new sinkings for the vitonballs!



From:
<https://iqwiki.iqo.uni-hannover.de/> - IQwiki

Permanent link:
https://iqwiki.iqo.uni-hannover.de/doku.php?id=groups:mg:project_ptb-cavity:labbook:2016-10:labbookentry-2016-10-19&rev=1477067643

Last update: 2016/10/21 16:34

